

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AP217
SW
1/4-1/2
0.337 mi.
1781 ft.

MANHOLE #TM2713
WEST 16TH ST/MERMAID AVE
BROOKLYN, NY

NY Spills S104788219
N/A

Site 3 of 4 in cluster AP

Relative:
Higher

Actual:
5 ft.

SPILLS:

Name: MANHOLE #TM2713
Address: WEST 16TH ST/MERMAID AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0005574 / 2001-11-07
Facility ID: 0005574
Facility Type: ER
DER Facility ID: 210712
Site ID: 257345
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2000-08-09
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-08-09
CID: 252
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-08-09
Spill Record Last Update: 2002-01-02
Spiller Name: RICHARD ROACHE
Spiller Company: MANHOLE #TM2713
Spiller Address: WEST 16TH ST/MERMAID AVE
Spiller Company: 001
Contact Name: RICHARD ROACHE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL e2mis notes: 50 gallons transformer oil on approx 100 gallons water in TM-2713. Transformer tested defective. Awaiting network crew to pressure test. Sample taken from structure. **Historical PCB count 12 ppm, transformer installed 1/1/91. Print shows sump but no sewer connection. 2000 hrs: Oil capacity of transformer is 340 gallons, and it was found to be 4 inches below minimum. 2 samples were taken, one from structure (went to Chem Lab first) and one from the unit. 2132 hrs: Tanker drained oil and water in manhole (450 gallons) also drained 345 gallons from transformer. There was about 35 gallons of oil in manhole. 2245 hrs: sample from manhole 12 ppm PCB. 8/10/00 0102 hrs: found cement sump in manhole. 0335 hrs: lab result from unit 1 ppm PCB. 1230 hrs: Transformer replaced, structure cleaned by double washing. "

Remarks:

"SPILL IS CONFINED TO MANHOLE-CLEAN UP IN PROGRESS 50-499PCB CON ED #132795."

All Materials:

Site ID: 257345
Operable Unit ID: 828138

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit: 01
Material ID: 546724
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 50.00
Units: G
Recovered: .00
Oxygenate: Not reported